

Project:

Bulk Asbestos Analysis

By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Customer: RPF Environmental Inc.

167213 SAU 3

320 1st NH Turnpike Northwood, NH 03261 Attn: Kara Forsythe

Lab Order ID: 1608477

Analysis ID: 1608477 PLM

Date Received: 5/2/2016

Date Reported: 5/3/2016 **Date Amended:** 5/4/2016

Sample ID	Description	Asbestos Fibrous		Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Aspestos	Components	Components	Treatment
041916 HG 1	Plaster with skim coat, 4th floor, closet outside room 402, wall	2% Chrysotile	3% Cellulose	85% Other 10% Quartz	Gray Non Fibrous Homogeneous
1608477PLM_1	single layer plaster				Crushed
041916 HG 1b	Plaster with skim coat, 4th floor attic stairwell, wall	2% Chrysotile	3% Cellulose	85% Other 10% Quartz	Gray Non Fibrous Heterogeneous
1608477PLM_2	single layer plaster				Crushed
041916 HG 1c	Plaster with skim coat, 3rd floor, room 301, wall	3% Chrysotile		97% Other	Tan Non Fibrous Homogeneous
1608477PLM_3	joint compound; not plaster				Crushed
041916 HG 1d	Plaster with skim coat, 3rd floor, ceiling, hallway	2% Chrysotile		88% Other 10% Quartz	Gray Non Fibrous Heterogeneous
1608477PLM_4	single layer plaster; small sample			.,. ¿	Crushed
041916 HG 1e	Plaster with skim coat, 2nd floor, north stairwell, ceiling	None Detected		100% Other	Gray Non Fibrous Heterogeneous
1608477PLM_5	single layer plaster; small sample				Crushed
041916 HG 1f	Plaster with skim, 1st floor, north stairwell, wall	3% Chrysotile		97% Other	Gray Non Fibrous Heterogeneous
1608477PLM_6	single layer plaster; small sample				Crushed
041916 HG 1g	Plaster with skim coat, 1st floor, ceiling, north stairwell	3% Chrysotile	3% Cellulose	94% Other	Gray Non Fibrous Heterogeneous
1608477PLM_7	single layer plaster; small sample				Crushed
041916 HG 2	Flooring paper, 4th floor, room 404	None Detected	80% Cellulose 10% Synthetic Fibers	10% Other	Tan Fibrous Homogeneous
1608477PLM_8	1		-		Ashed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Megan Javonovich (13)

Analyst

Approved Signatory



Project:

Bulk Asbestos Analysis



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: RPF Environmental Inc.

167213 SAU 3

320 1st NH Turnpike Northwood, NH 03261 Attn: Kara Forsythe

Lab Order ID: 1608477

Analysis ID: 1608477 PLM

Date Received: 5/2/2016

Date Reported: 5/3/2016

Date Amended: 5/4/2016

Sample ID Lab Sample ID	Description Lab Notes	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes Treatment
041916 HG 2b	Flooring paper, 4th floor, room 404	Not Analyzed			
1608477PLM_9	no sample in bag				
041916 HG 100	Flooring paper, gymnasium, under bleechers	None Detected	90% Cellulose	10% Other	Tan, Black Fibrous Homogeneous
1608477PLM_10	-				Ashed
041916 HG 100b	Flooring paper, gymnasium, under bleechers	None Detected	90% Cellulose	10% Other	Tan, Black Fibrous Homogeneous
1608477PLM_11	-				Ashed
041916 HG 101	Vapor barrier, gymnasium, under bleechers	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
1608477PLM_12					Dissolved
041916 HG 101b	Vapor barrier, gymnasium, under bleechers	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
1608477PLM_13	-				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Megan Javonovich (13)

Approved Signatory

Client:	RPFEnvironmental, Inc.	*Instructions:	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
Contact:	Kara Forsythe	Use Column "B" for your contact info	Scientific Analytical
	320 First NH Turnpike Northwood,		
Address:	NH 03216		
Phone:	603-942-5432	To See an Example Click the	Institute, Inc.
Fax:	603-942-5300	bottom Example Tab.	
Email:	kara@airpf.com		302-L Pomona Dr.
		Enter samples between "<<" and ">>"	Greensboro, NC 27407
Project:	167213 SAU 3	Begin Samples with a "<< "above the first sample	Phone: 336.292.3888
4 5 5 SAM		and end with a ">>" below the last sample.	Fax: 336.292.3313
	All samples Composite unless	朱 : 一, 此 自 :	
CALL THE STATE	otherwise noted. Stop at first		
Client Notes:	positive	Only Enter your data on the first sheet "Sheet1"	Email: lab@sailab.com
P.O. #.		Note: Data 1 and Data 2 are optional	
Date Submitted:	4.29.16	fields that do not show up on the official	
		report, however they will be included	
Analysis:	PLM	in the electronic data returned to you	
TurnAroundTime:	48 hrs	to facilitate your reintegration of the report data.	

Sample Number Data 1	Sample Description	Data 2		
<<				
	Plaster with skim coat, 4th floor, closet	outside room		
041916 HG 1	402, wall	, and the same of		
041916 HG 1b	Plaster with skim coat, 4th floor attic sta	Plaster with skim coat, 4th floor attic stairwell, wall		
041916 HG 1c	Plaster with skim coat, 3rd floor, room 3	Plaster with skim coat, 3rd floor, room 301, wall		
041916 HG 1d	Plaster with skim coat, 3rd floor, ceiling	Plaster with skim coat, 3rd floor, ceiling, hallway		
041916 HG 1e	Plaster with skim coat, 2nd floor, north	Plaster with skim coat, 2nd floor, north stairwell, ceiling		
041916 HG 1f	Plaster with skim, 1st floor, north stairw	Plaster with skim, 1st floor, north stairwell, wall		
041916 HG 1g	Plaster with skim coat, 1st floor, ceiling,	, north stairwell		
041916 HG 2	Flooring paper, 4th floor, room 404			
041916 HG 2b	Flooring paper, 4th floor, room 404	turned to dust may not be enough		
Hillside	- 5 m el	1 0/2 0/11/11/11		

Accepted M M8Cuuy Rejected D 5/2 9:35 Am

1608477

041916 HG 100 041916 HG 100b 041916 HG 101 041916 HG 101b >> Flooring paper, gymnasium, under bleechers Flooring paper, gymnasium, under bleechers Vapor barrier, gymnasium, under bleechers Vapor barrier, gymnasium, under bleechers