

# City of Berlin Fire Department Inspection Report **2018**

City of Berlin Brown Elementary School Date: October 4, 2018  
Address: 190 Norway Street Owner: City of Berlin SAU3  
Occupant: Brown Elementary School Purposed use: Educational – Brown School/POS  
Bldg. Type: Type III/2 Stories Roof Construction: Rubber  
Roof – Pitched or Flat: Pitched & Flat Stairway Locations: Old Building – North and South  
Opened or Closed: Open Fire Doors: Yes Fire Escapes: N/A  
Number: N/A Location: N/A Material: N/A  
Condition: N/A Exit Doors Proper Hardware: Yes  
Exit ways Properly Marked and Light: Yes: Adequate Exits: Yes  
No. of Fire Extinguisher: 11 Type: ABC, K Condition: Good Where Required: Yes  
Automatic Sprinklers: Yes Location of FD Connection: AD Side of old Bldg.  
Standpipes: No Location: N/A Condition: N/A  
Fire Alarm: Yes, Master Box #124 Does it Operate: Yes  
Electrical System Properly Fused: Appears to be  
Heating Apparatus: Hot Water Type: Gun Fuel: No. 2 Heating Oil  
Fuel Storage: 7,000 gallons Where: Underground/Norway St. Side  
Other Fuels: 250lbs. LPG Emergency Lights: Yes Smoke Doors: Yes

- Junction box cover missing in Room #305
- Second floor hallway exit sign non-functional near Room #303.
- Hallway outlet broken near Room #402.
- Front hallway near Door C, exit sign non-operational.
- Exit Light in cafeteria/gymnasium near kitchen is non-operational.

Inspector: 

The above violations shall be corrected in accordance with the authority of the New Hampshire Statues, Chapter 153:16 Revised Laws.

Received by: 

Reinspected

Violations Corrected

**"Any violations and/or hazardous conditions which has been accidentally overlooked does not imply approval of such violations or conditions"**

BERLIN FIRE DEPARTMENT  
BUILDING INSPECTION REPORT

City or Town BERLIN Date 10/4/2018  
Street and Number 190 NORWAY STREET  
Owner CITY OF BERLIN SAU 3 Occupant BROWN ELEMENTARY SCHOOL  
Purpose Used EDUCATIONAL / PDA Type of Bldg: TYPE III Stories 2  
Kind of Roofing FLAT RUBBER Pitch or Flat BOTH  
Stairway Location NORTH SOUTH IN OLD BUILDING Open Closed Fire Doors  
Fire Escapes N/A  
Number N/A Iron Wood Location Condition  
Are Exit Doors Equipped with Panic Hardware where Needed? YES  
Are all Exit ways Properly Marked and Lighted? YES Are Exits Adequate? YES  
Fire Extinguishers 11 No Kind ABC Condition GOOD Placed where necessary? YES  
Automatic Sprinklers Yes No Location of Outside connections: NORWAY ST. SIDE / OLD BLDG.  
Standpipes and Hose Yes No Location Condition  
Fire Alarm Yes No BOX 124 Will it Operate? YES  
Are Electric Lighting and Appliance Circuits Fused Correctly? APPEAR TO BE 15 amp or less  
Heating Apparatus: Oil Gas Coal Other LPG TANKS FOR CAFE / NORTH SIDE  
Type COLD / HOT WATER Fuel Storage 2000 GALLONS Where UNDERGROUND  
Emergency lights YES Smoke doors YES

COMMENDATIONS:

- JUNCTION BOX COVER MISSING ROOM #305
- SECOND FLOOR HALLWAY EXIT SIGN NON-FUNCTIONAL (NEAR RM 303)
- HALLWAY OUTLET BROKEN NEAR ROOM 402
- FRONT HALLWAY NEAR DOOR C EXIT SIGN NON-OPERATIONAL
- EXIT LIGHT IN CAFE/TERIA NEAR KITCHEN NON-OPERATIONAL

Re-inspected

Recommendations completed

"ANY VIOLATIONS AND/OR HAZARDOUS  
CONDITION WHICH HAS BEEN ACCIDENTALLY  
OVERLOOKED DOES NOT IMPLY APPROVAL OF  
"H VIOLATION OR CONDITION"

Inspector

